INTERSTATE NUCLEAR SERVICES
A SUBSIDIARY OF UNIFIRST CORPORATION

DL-040998_02

April 9, 1998

Mr. Bryan Parker
US Nuclear Regulatory Commission, Region II
101 Marietta Street, Suite 2900
Atlanta, GA 30323-0199

RE: Decommissioning Plan dated March 20, 1998

Dear Mr Parker.

The Decommissioning Plan that INS submitted dated March 20, 1998, erroneously referenced license 39-19727-01. Upon investigation it was discovered that the renewal application and license appendices submitted in support of the license dated October 1, 1992, as well as the other letters referenced in license condition 19 of license 20-25222-01, all reference the incorrect license number. The correct license number of the Portsmouth, Virginia facility is 20-25222-01. All other information submitted is accurate, and all documents incorporated into the license will remain in full force during decommissioning as indicated in the decommissioning plan

Thank you for your assistance in this matter. I apologize for any inconvenience and confusion these errors may have caused

Sincerely,

Glenn Roberts
INS Corporation
Health Physicist

2:99/804099GR.wpd

295 Parker Street • P.O. Box 51957 • Springfield Massachusetts 01151 • (413) 543-6911 • FAX (413) 543-6989 • e-mail ns@u1st.com